Revision B. Do not clean electronic throttle bodies with a wire brush.